




The Quick Connect  
Solution Provider




# CEJN Alert Ring

*- Visual safeguards to ensure proper connection*

## ENSURE PROPER CONNECTION

In rough and stressful work environments there is always a risk that the coupling may not be completely connected, CEJN alert ring is a visual safeguard to ensure proper connection. If the red ring is visible, the coupling isn't connected.



**The following series will be introduced in the second quarter of 2013:  
115, 116, 117, 125, 135 and 218**

